SHUTTLE CRITICAL ITEMS LIST - MSBLS GROUND STATION

SUBSYSTEM: GROUND STATION - MSBLS FMEA NO.: 05-25W-00003 Rev: 9 April 90

ASSEMBLY: PRI Shelter ABORT: CRIT. FUNC: 1R

P/N : 517070 CRIT. HDW: 2 • VEHICLE 102 103 104 105

QUANTITY: 1 EFFECTIVITY: X X X X X PHASE(S) PL LO CO DO X LS

REDUNDANCY SCREEN: A-pass B-pass C-pass

PREPARED BY:

APPROVED BY (NASA)

DES: VILLE DES: APPROVED BY (NASA)

REI: OE: Paul 300 DE: C. Stughou

FIEM: PRI Shelter

FUNCTION: Provides Azimuth and IME guidance RF beams to Orbiter.

FAILURE MODE: No Azimuth and/or DME guidance RF is radiated to Orbiter from Shelter.

CAUSE(S): A Shelter IRU (AZ or DME subsystem) fails due to piece part electrical failure. The IRU's which can cause this failure mode (05-25W-00003) are listed below, with IRU Designator No., IRU P/N, and IRU Name:

| IRU No.: | LRU P/N: | IRU Name: |
|----------|--------------------|--|
| 140 | 501808 | Transmitter, Azimuth/DME |
| 160 | 501825 | Power Supply |
| 301 | 502156 | Air Conditioner (two of two failures required) |
| 322 | 517076 | |
| 324 | 51707 9 | Cables, Interconn, Interior (inside Shelter) |
| 325 | 517081 | Harness, Rack |
| | 517082 | |
| 519 | 513479 | Digital Unit, Azimuth |
| | 511219 | |
| 550 | 502332 | Field Monitor Circuits, Azimuth/DME |
| 580 | 502146 | DME Unit |
| 630 | 501771 | · |
| 640 | 502541 | Assy, Waveguide (AZ) |
| 641 | 502232 | |
| 705 | 502544 | Assy, Waveguide (DME) |
| 707 | 513888 | Radome, Azimuth |
| 710 | 517080 | Cables, Intercorn, External (to/from Shelter) |
| 862 | 513274-1 | |
| 863 | 513455 | |
| 864 | 513456 | |
| 920 | 518007 | Assy, RF (Switching) |

SHUTTLE CRITICAL ITEMS LIST - MSBLS CROUND STATION

FMEA NO.: 05-25W-00003 Rev: 9 April 90 SUBSYSTEM: CROUND STATION - MSBLS SUP: 17 Oct 88

EFFECT(S): (A) SUBSYSTEM (B) INTERFACES (C) MISSION (D) CREW/VEHICLE

- (A/B) All RF output from the PRI Shelter ceases, but RF guidance is immediately (within one second) replaced by RF guidance from the B/U Shelter. However, redundancy has been lost, and the next failure (if in B/U Shelter) will cause loss of good RF guidance.
- (C) Not applicable.
- (D) No effect beyond momentary (less than one second) loss of AZ/DME RF quidance signals at the Orbiter. Possible loss of crew/vehicle after second failure (loss of PRI and B/U) due to loss of good AZ/DME RF quidance signals at the Orbiter.

DISPOSTION AND RATIONALE:

- (A) DESIGN (B) TEST (C) INSPECTION (D) FAILURE HISTORY (E) OPERATIONAL USE
- (A) DESIGN The MSBIS design was structured from existing/proven ground-based landing systems and upgraded to meet MII-E-4158, MII-SID-454 and all subsidiary specifications in effect at the time of manufacture. Military and standard NASA approved parts, materials and processes were used.

The design evolved from a timely and in-depth internal design review process culminating in an optimum reliability/maintainability/performance end-item product. The design review process included studies such as FMEA, electrical and thermal analysis, smeak circuit analysis, worst case studies, tolerance analysis, etc. which resulted in direct impact of the design.

The design was approved via the formal NASA-CSD FOR, CDR, FCA and certification process.

(B) - TEST The MSBLS program consists of an equipment confidence build-up approach starting from 100% screening of components (burn-in and environmental test). Environmental testing of SRU's and 100% temperature/vibration tests at the LRU and equipment rack-level.

In plant ATP for functional performance verification and workmanship will be performed and witnessed by CSD, NASA and DCAS on all IRUs and again at system level.

Site testing and certification will be performed on each system after installation. Annual flight tests are conducted to demonstrate continued system compatibility.

Ground Turnaround Test - Verify operation of the MSBIS Ground Station prior to each Orbiter landing.

SHUTTLE CRITICAL ITEMS LIST - MSBLS GROUND STATION

SUBSYSTEM: GROUND STATION - MSBLS FMEA NO.: 05-25W-00003 Rev: 9 April 90

SUP: 17 Oct 88

(C) - INSPECTION

Receiving Inspection

Receiving inspection verifies all incoming parts and materials, including the performance of visual and dimensional examinations. All electrical, mechanical and raw material records that certify materials and physical properties per drawing/specification requirements are retained by receiving inspection as required by contract.

Assembly/Installation

All detailed inspections are planned out by the methodization department for all new builds, spares and repairs for the MSRIS Programs. Inspection points are designated to permit inspection before the applicable portions of the assembly become inaccessible and prior to the next assembly operation.

Critical Processes

All processes and certifications are monitored and verified by inspection. The critical processes are soldering, conformal coating, torquing and boresiting, application of adhesives/sealants and application of chemical film.

Testina

All parts of the ATP are observed and verified by QA.

Handling/Packaging

All parts and assemblies are protected from damage or contamination from the point of receiving inspection to final shipment, through methods detailed in a documented procedure. This handling procedure is in effect for all newly built hardware as well as for repair units. QA audits conformance to this procedure in accordance with its internal audit schedule, and all areas are considered under continuous audit by QA with respect to material handling. The maintenance of electrostatic discharge prevention methods is verified by QA through periodic audits. All hardware items are packaged and protected according to contract requirements and are verified by inspection. Evidence of inspection of packaging is recorded on the applicable shipping document.

SHUTTLE CRITICAL ITEMS LIST - MSBLS GROUND STATION

SUBSYSTEM: GROUND STATION - MSBLS FMEA NO.: 05-25W-00003 Rev: 9 April 90 SUP: 17 Oct 88

(D) - Failure History All field and flight failures were reviewed. The failures identified occurred in cicuitry identical to the current hardware configuration; MSBLS-GS and MSBLS-JR failures are included. There have been 7 failures in the power entrance panel resulting in the loss of power to the shelter. There have been 55 failures resulting in the loss of output from the shelter. Due to limitations in the current repair contract, no failure analysis results are available for the 48 reported transmitter failures. From the problem descriptions it is felt that nearly half of the transmitter failures were due to end of life conditions on the magnetron tubes. In addition, there have been 6 power supply failures, 1 intermittent waveguide switch problem, and 1 failure caused by a defective weld in a directional coupler. There have been 11 single air conditioner failures which resulted in the potential shutdown of the shelter, if 2 air conditioners had failed in a single shelter. Icss of output failures typically are detected at systems power up, and generally do not occur during system operation. Since MSRIS Ground Stations are powered up daily beginning 4 or 5 days prior to a mission, and again 4 hours before a landing, a loss of output failure most likely would be detected and corrected before a Shuttle landing.

(E) - OPERATIONAL USE
For lower ceilings (8,000 to 10,000 feet) or night operations, redundant
MSBLS (single fault tolerance) is required for night landing on a
concrete nurway. MSBLS is also mandatory for daylight landings on the
lakebed with reduced ceilings, but is not required to be redundant.
Deorbit is not attempted if the ceiling is less than 8,000 feet to ensure
good visibility at low altitude. If radar tracking data (available at
Edwards, KSC, and Northrop only) and ground communications are available,
the MCC can attempt to resolve a MSBLS dilemma. Remote control operators
are trained to evaluate system health and recognize probable failure
modes from the Remote Control Unit Display. The Remote Control Operators
will verify the back-up switching transition has occurred properly or
take action to force the system into back-up. The Remote Control Unit
Display is monitored to determine a malfunction and advise the chain of
command on the status.